


MONUMENT RECORD

STATE OF INDIANA ~ COUNTY OF MONROE

Section 2, Township 9 North, Range 2 West,

Monument Description & Remarks: Found Railroad Spike at West 1/4 Corner,
0.8' North of centerline (Maple Grove Rd.) and 2.5" deep.



I, Ben E. Bledsoe, Registered Land Surveyor, here by certify that this document was prepared under my direction in accordance with the provisions of Section 17-3-64-4 through 17-3-64-8 of the Indiana Code, being Acts of 1965, Chapter 319; this 6th day of January, 2005 A.D.

Ben E. Bledsoe

Indiana Registered Land Surveyor No. S0559



MONUMENT RECORD

Corner I.D. #


Q-3

STATE OF INDIANA - COUNTY OF MONROE

Section Two (2), Township 9 North, Range 2 West

Monument Description & Remarks: Found Railroad Spike at West 1/4 Corner,
.8' North of centerline (Maple Grove Rd.) and 2.5" deep. Survey marker
sign set 14.24', N 04° W, in Board Fence, 4.4' up.

Recovery Tie Drawing



State of Indiana
 County of Monroe

Space
 Reserved For
 Recording
 Officer

I, Michael W. Friley, County Surveyor, hereby certify
 that this document was prepared under my direction in
 accordance with the provisions of Section 17-3-64-4
 through 17-3-64-8 of the Indiana Code, being Acts of 1965,
 Chapter 319; and the above data is given under my hand and
 seal this 10th day of October, 1995 A.D.

Indiana Registered Land Surveyor No. _____ or

Monroe County Surveyor's Office

United States Government Agency

Monroe County Surveyor

Title

Field Book:

96-01

Page:

50-51